

Oil Field Environmental Incident Summary

Incident: 20160923101430

Date/Time of Notice: 09/23/2016 10:14

Responsible Party: BERENERGY CORPORATION

Well Operator: BERENERGY CORPORATION

Well Name: C. M. REIQUAM-STATE 3

Field Name: GLENBURN

Well File #: 8345

Date Incident: 9/20/2016

Time Incident: 07:00

Facility ID Number:

County: BOTTINEAU

Twp: 159

Rng: 82

Sec: 36

Qtr: SE SW

Location Description:

Submitted By: William Braden

Received By:

Contact Person: William Braden

7114 W JEFFERSON AVE STE 206

LAKEWOOD, CO 80235

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building: 830 Feet

Distance Nearest Water Well: 7535 Feet

Type of Incident: Pipeline Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3	Barrels	3	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

15' x 30'

Potential Environmental Impacts:

oil impacted soil

Action Taken or Planned:

Oil impacted soil was scraped up and a berm placed around it and the flow line was isolated. Approximately 1.5 yards of oil impacted soil was scraped up and stored in 7 barrels. A dig request was submitted and the flow line will be excavated and repaired after the required notice period has passed. Any additional oil impacted soil will be excavated and properly disposed of along with the oil impacted soil currently being stored or stockpiled.

Wastes Disposal Location: All of the oil impacted soil will be hauled to the Clean Harbors landfill in Sawyer, ND for disposal.

Agencies Involved:**Updates**

Date: 9/23/2016 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a pipeline leak, was not contained according to the report. Further follow-up needed.

Date: 9/26/2016 **Status:** Inspection

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 14:30. 65 degrees F, sunny, northwest wind 15-25 mph. Observed the site and took photos. It appeared the release occurred north of the well pad in cultivated farmland. Oil-covered grain shovels had been left next to an area approximately 30' by 20' which had about 2 to 3 inches of topsoil removed (some oil staining remained in that area). Directly east of the shoveled area and adjacent to it was an earthen berm that held an approximate area of 5' by 6' of standing oil. More follow-up will be needed.

Date: 10/4/2016 **Status:** Inspection

Author: Washek, Sandi

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 11:19 a.m. Wind out of the west at 21 mph, and temperature was 61 degrees F. N 48.54738 by W101.20353.

Area surrounding the site has been dug up, and it appeared some soil has been removed. There was still stained soil near the wellhead and an oil-stained barrel/shovels on site. The area had received rain in the past days, and inspection of the water puddles showed no visible sheen on any of them.